

Labor and Materials

Copper } Connection.....	3	\$ 2.60
Curb } Cock Valve }.....	1	\$ 2.77
} T.S. & V. }.....		
Service Box } Short 3/4 x 4 1/2 }.....		\$ 1.38
Old returned } Long 4 1/2 x 6 1/2 }.....		
} Buff or Rdway }.....		
30 1/2 Ft. } 3 1/4 in. } Copper Galv. Iron } Pipe at.....	3	\$ 4.68
} Cast Iron }.....		
Nipples..... in. at.....		\$
Bushings..... to..... in. at.....		\$
Red'g } Couplings..... to..... in. at.....		\$
Inc'g }.....		
Union..... in. at.....		\$
Meter..... in. at.....		\$
Lbs. Br. Stone at.....		\$
Lbs. Sand at.....		\$
Bags Cement at.....		\$
Paving Brick } Mack } at.....		\$
} Red }.....		
} Asphalt }.....		
Lead Joints at.....		\$
Leadite Joints at.....		\$
4 Hrs. Foreman at.....		\$ 2.50
4 Hrs. Common Labor at.....		\$ 2.00
9 Hrs. Common Labor at.....		\$ 4.05
Hrs. Mason at.....		\$
Hrs. Mason's Helper at.....		\$
Hrs. Compressor at.....		\$
Compensation Ins.....		\$ 76
Trucking.....		\$ 5.00
Builders' Use of Water.....		\$ 5.00
Total \$		25.74

31-220 16

Labor and Material Report

Oct 23 1901

22 Oak St



6" Main

Elev of Main at tap

Gate at ●

● Gate at

● Curb Box

old Tap shut

Tax W# 303.17-19-5