

Labor and Materials

1	Copper } Connection.....	\$ 320
	Lead }	
1	Curb { Cock }	\$ 1.00
	{ Valve }	
	{ T. S. & V. }	
1	Service Box { Short 3 1/2 x 4 1/2 }	\$ 1.40
	{ Long 4 1/2 x 5 1/2 }	
	Old returned { Buff. or Rdway }	
12	Pt. in. { Copper } Pipe at.....	\$ 264
	{ Galv. Iron }	
	{ Cast Iron }	
	Nipples..... in. at.....	\$
	Bushings..... to..... in. at.....	\$
	Red'g } Couplings..... to..... in. at.....	\$
	Inc'g }	
	Union..... in. at.....	\$
	Meter..... in. at.....	\$
	Lbs. Br. Stone at.....	\$
	Lbs. Sand at.....	\$
	Bags Cement at.....	\$
	Paving Brick { Mack } at.....	\$
	{ Red }	
	{ Asphalt }	
	Lead Joints at.....	\$
	Leadite Joints at.....	\$
	Hrs. Foreman at.....	\$
13	Hrs. Common Labor at.....	\$ 528
	Hrs. Common Labor at.....	\$
	Hrs. Mason at.....	\$
	Hrs. Mason's Helper at.....	\$
	Hrs. Compressor at.....	\$
	Compensation Ins.....	\$ 14
1	Trucking	\$ 1.00
	Builders' Use of Water.....	\$
Total \$		1466

Labor and Material Report

79

June 27 1920

79 79 1st St.

