

LABOR AND MATERIALS

Copper } Connection	\$
Lead }	\$
Curb { Clock Valve }	in. \$
{ T. S. & V. }	in. \$
Service box } Short 3/4X4/4 }	\$
Old returned } Long 4/4X5/4 }	\$
{ Buff or Rdway }	\$
Ft. in. } Copper } Pipe at	\$
{ Galv. Iron }	\$
{ Cast Iron }	\$
Nipples	in. at \$
Bushings	to in. at \$
Red'g } Couplings	to in. at \$
Inc'g }	to in. at \$
Union	in. at \$
Meter	in. at \$
Lead Joints at	\$
Compound Joints at	\$
Hrs. Foreman at	\$
Hrs. Chauffeur at	\$
Hrs. Tapper at	\$
Hrs. Labor at	\$
Hrs. Labor at	\$
Hrs. Compressor at	\$
Compensation Ins.	\$
Trucking	\$
Builders Use of Water.	\$
<i>Warskiuskat G. E.</i>	\$
.....	\$
.....	\$
.....	\$
.....	\$
.....	\$
.....	\$

Oakland

St. _____
Pl. _____
Ave. No. *5*

Name of Owner _____

Labor and Mat'l. Report *July* 19*45*



Main _____ Elev. of Main at tap _____
Gate at ● _____ Gate at ● _____

● Curb Box