

**Labor and Materials**

|    |  |          |
|----|--|----------|
| 1  | Copper } Connection.....                   | \$ 3.20  |
|    | Lead } .....                               |          |
| 1  | Curb { Cock } .....                        | \$ 1.50  |
|    | { Valve } .....                            |          |
|    | { T. S. & V. } .....                       |          |
| 1  | Service Box { Short 3 1/2 x 4 1/2 } .....  | \$ 1.40  |
|    | Old returned { Long 4 1/2 x 5 1/2 } .....  |          |
|    | { Buff. or Rdway } .....                   |          |
| 11 | Ft. .... in. { Copper } Pipe at.....       | \$ 2.42  |
|    | { Galv. Iron } .....                       |          |
|    | { Cast Iron } .....                        |          |
|    | Nipples..... in. at.....                   | \$ ..... |
|    | Bushings..... to..... in. at.....          | \$ ..... |
|    | Red'g } Couplings..... to..... in. at..... | \$ ..... |
|    | Inc'g } .....                              |          |
|    | Union..... in. at.....                     | \$ ..... |
|    | Meter..... in. at.....                     | \$ ..... |
|    | Lbs. Br. Stone at.....                     | \$ ..... |
|    | Lbs. Sand at.....                          | \$ ..... |
|    | Bags Cement at.....                        | \$ ..... |
|    | Paving Brick { Mack } at.....              | \$ ..... |
|    | { Red } .....                              |          |
|    | { Asphalt } .....                          |          |
|    | Lead Joints at.....                        | \$ ..... |
|    | Leadite Joints at.....                     | \$ ..... |
|    | Hrs. Foreman at.....                       | \$ ..... |
| 13 | Hrs. Common Labor at.....                  | \$ 5.28  |
|    | Hrs. Common Labor at.....                  | \$ ..... |
|    | Hrs. Mason at.....                         | \$ ..... |
|    | Hrs. Mason's Helper at.....                | \$ ..... |
|    | Hrs. Compressor at.....                    | \$ ..... |
|    | Compensation Ins.....                      | \$ ..... |
| 1  | Trucking .....                             | \$ 1.00  |
|    | Builders' Use of Water.....                | \$ ..... |
|    | <b>Total</b> \$ .....                      | \$ 4.44  |

**Labor and Material Report**

58

June 27 1927

3/4 tap 58 ~~Oakland~~ ~~Street~~



Main

Elev. of Main at tap

Gate at ●

● Gate at

● Curb Box

Curb box and rod removed  
9-22-60.  
Curb Cock  
Under sidewalk.