

Labor and Materials

1	Copper	Connection	3	\$ 2.70
1	Curb	Cock Valve	3	\$ 2.39
1	Service Box	Short 3/4 x 1/2		
	Old returned	Long 1/2 x 1/2		
		Ball on Red way		\$ 1.45
2	Ft.	Copper Galv. Iron Cast Iron	3	\$ 5.67
1	Nipples	in. at		\$
1	Bushings	to 1/2 in. at	3	\$.10
	Red'g Inc'g	Couplings to in. at		\$
	Union	in. at		\$
	Meter	in. at		\$
	Lbs. Br. Stone	at		\$
	Lbs. Sand	at		\$
	Bags Cement	at		\$
	Paving Brick	Mack Red Asphalt at		\$
	Lead Joints	at		\$
	Leadite Joints	at		\$
3	Hrs. Foreman	at		\$ 1.88
6	Hrs. Common Labor	at Taper		\$ 3.00
6	Hrs. Common Labor	at		\$ 2.70
	Hrs. Mason	at		\$
	Hrs. Mason's Helper	at		\$
	Hrs. Compressor	at		\$
	Compensation Ins			\$ 2.3
	Trucking			\$ 1.00
	Builders' Use of Water	Patch		\$ 5.00
Total \$				76.12

30-68

Labor and Material Report

June 24, 1930

6 Almer Street

11' 4"



19' 6"

W Main

Elev of Main at tap 5 1/2

Gate at

TAX ID # 309.7-11-2

Gate at

Curb Box

all tap disconnected

21' MAIN