

LABOR AND MATERIALS

1 ~~Copper~~ } Connection $\frac{3}{4}$ " \$ _____
 ~~Lead~~ }
 1 Curb } Cock Valve } $\frac{3}{4}$ in. \$ _____
 } T. S. & V. }
 1 Service box } Short $3\frac{1}{2} \times 4\frac{1}{2}$ }
 Old returned } Long $4\frac{1}{2} \times 5\frac{1}{2}$ }
 } Buff or Rdway } \$ _____
 26 Ft. $\frac{3}{4}$ in. } Copper } Pipe at \$ _____
 } C.I. }
 } C.I. }
 _____ Nipples _____ in. at \$ _____
 _____ Bushings _____ to _____ in. at \$ _____
 _____ Red'g }
 _____ Inc'g } Coupl'gs _____ to _____ in. at \$ _____
 _____ Union _____ in. at \$ _____
 _____ Meter _____ in. at \$ _____
 _____ Lead Joints at \$ _____
 _____ Compound Joints at \$ _____
 _____ Maintenance Foreman \$ _____
 _____ Hrs. Water Maint. Man—1 at \$ _____
 _____ Hrs. Water Maint. Man—2 at \$ _____
 _____ Hrs. Garage Foreman _____ at \$ _____
 _____ Hrs. Labor— _____ at \$ _____
 _____ Hrs. Compressor at \$ _____
 _____ Compensation Ins. at \$ _____ per C \$ _____
 _____ Trucking _____ \$ _____
 _____ Pav't Patch _____ \$ _____
 Tap by Miller T Co. \$ _____
 5-29-57 \$ _____
 _____ \$ _____
 _____ O'head _____ \$ _____
 _____ \$ _____

St.
 PI
 Ave. No. 30

Name of Owner F. Karl Supremant

Labor and Mat'l. Report May 29 19 57

#30

49'9"

44'5"

● Curb Box

6" Main Elev. of Main at tap 4 1/2'

Gate at ● ● Gate at

TAX ID# 303.13-13-11

● Curb Box

LSM-SC-2-5-56