

LABOR AND MATERIALS

1 Copper } Connection	\$ 1.31
1 Lead } Connection	
1 Curb } Cock Valve	\$ 1.75
1 Curb } F. S. & V.	
1 Service Box } Short 3 1/2 x 4 1/2	\$ 1.60
1 Old returned } Long 4 1/2 x 5 1/2	
1 Old returned } Buffer Rdway	
25 Ft. 3/4 in. } Copper Galv-Iron	\$ 4.50
25 Ft. 3/4 in. } Cast-Iron	
Nipples in. at	\$
Bushings to in. at	\$
Red'g Inc'g } Couplings to in. at	\$
Union in. at	\$
Meter in. at	\$
Lead Joints at	\$
Leadite Joints at	\$
Hrs. Foreman at	\$ 6.3
Hrs. Chauffeur at	\$ 4.7
3/4 Hrs. Tapper at	\$ 6.75
15 Hrs. Labor at	\$
Hrs. Labor at	\$
Hrs. Compressor at	\$ 2.7
Compensation Ins.	\$ 1.00
Trucking	\$
Builders Use of Water	\$
	\$
	\$
	\$
Tap by Penar	\$ 18.28

137 - 1940

St.
Pt.
Ave. No. 16

Name of Owner

Labor and Mat'l. Report NOV 7 - 1940 19

