

LABOR AND MATERIALS

1 Copper Connection $\frac{3}{4}$ " \$ _____
 1 Lead }
 1 Curb } Cock } $\frac{3}{4}$ in. \$ _____
 } Valve }
 } T.S. & V. }
 1 Service box { Short $3\frac{1}{2}$ x $4\frac{1}{2}$ }
 Old returned { Long $4\frac{1}{2}$ x $5\frac{1}{2}$ } \$ _____
 } Buff or Rdway }
 2.5 Ft. $\frac{3}{4}$ in. { Copper } Pipe at \$ _____
 { G.I. }
 { C.I. }
 Nipples in. at \$ _____
 Bushings to in. at \$ _____
 Red'g }
 Inc'g } Coupl'gs. to in. at \$ _____
 Union in. at \$ _____
 Meter in. at \$ _____
 Lead Joints at \$ _____
 Compound Joints at \$ _____
 Maintenance Foreman \$ _____
 Hrs. Water Maint. Man-1 at \$ _____
 Hrs. Water Maint. Man-2 at \$ _____
 Hrs. Garage Foreman at \$ _____
 Hrs. Labor at \$ _____
 Hrs. Compressor at \$ _____
 Compensation Ins. at \$ _____ per C \$ _____
 Trucking \$ _____
 Pav't Patch \$ _____
 Tappy Giscardt \$ _____
 Co. 6-27-58 \$ _____
 O'head \$ _____
 \$ _____

✓
 Orchard St. Pt. 60-62 Ave. No.
 Name of Owner Elmer Norris
 Labor and Mat'l. Report June 27 1958
 #60-62

 45'
 55' 5"
 ● Curb Box
 6" Main Elev. of Main at tap 5 1/2'
 Gate at ● Gate at ●
 ● Curb Box
 #60 TAX ID# 303.13-21-4
 LSM-5C-2-B 56