

**Labor and Materials**

1. Copper } Connection <i>3/4</i>	\$ 320
Lead } <i>3/4</i> in.	\$ 1.00
1. Curb { Cock } <i>3/4</i> in.	\$ 1.40
{ Valve }	
{ T.S. & V. }	
1. Service Box { Short <del>3 1/2</del> x 4 1/2 }	\$ 1.40
Old returned { Long 4 1/2 x 5 1/2 }	
{ Buff. or Rdway }	
10. Ft. in. { Copper } Pipe at	\$ 2.20
{ Galv. Iron }	
{ Cast Iron }	
Nipples in. at	\$ .07
1. Bushings <i>3/4</i> to <i>1/2</i> in. at	\$ .07
Red'g } Couplings to in. at	\$
Inc'g }	
Union in. at	\$
Meter in. at	\$
Lbs. Br. Stone at	\$
Lbs. Sand at	\$
Bags Cement at	\$
Paving Brick { Mack } at	\$
{ Red }	
{ Asphalt }	
Lead Joints at	\$
Leadite Joints at	\$
14. Hrs. Foreman at <i>G.2.W-</i>	\$ 8.75
Hrs. Common Labor at	\$
Hrs. Common Labor at	\$
Hrs. Mason at	\$
Hrs. Mason's Helper at	\$
Hrs. Compressor at	\$
Compensation Ins.	\$ 23
Trucking	\$ 1.50
Builders' Use of Water	\$
<b>Total</b>	<b>\$ 17.85</b>

27-65 23  
**Labor and Material Report** *June 7* 1927

*11 Orchard St*



*4 in* Main Elev. of Main at tap *4 1/2*

Gate at ● ● Gate at

● Curb Box

*Old tap Duroc  
 std  
 TAX 10# 303.18-5-12*