

LABOR AND MATERIALS

| | | | | | | | |
|----|-----------------------|-------|----------------|---------------|----------|------|----|
| 1 | Copper | { | Same Bull Head | Connection | Coupling | 3/4" | \$ |
| 1 | Lead | { | Cock Valve | T.S. & V. | 3/4" | in. | \$ |
| 1 | Service box | { | Short | 3 1/2 x 4 1/2 | | | \$ |
| | Old returned | { | Long | 4 1/2 x 5 1/2 | | | \$ |
| | | | Buff or Rdway | | | | \$ |
| 12 | Ft. | 3/4" | Copper | C.I. | Pipe | at | \$ |
| | Nipples | in. | at | | | | \$ |
| | Bushings | to | in. | at | | | \$ |
| | Red'g | { | Coupl'gs | to | in. | at | \$ |
| | Inc'g | | | | | | \$ |
| | Union | in. | at | | | | \$ |
| | Meter | in. | at | | | | \$ |
| | Lead Joints | at | | | | | \$ |
| | Compound Joints | at | | | | | \$ |
| | Hrs. Water Maint. Man | —1 | at | | | | \$ |
| | Hrs. Water Maint. Man | —2 | at | | | | \$ |
| | Hrs. Labor | — | at | | | | \$ |
| | Hrs. Labor | — | at | | | | \$ |
| | Hrs. Compressor | at | | | | | \$ |
| | Compensation Ins. | at \$ | per C. | | | | \$ |
| | Trucking | | | | | | \$ |
| | Pay't Patch | | | | | | \$ |
| | Tap by Moquin | | | | | | \$ |
| | O'head | | | | | | \$ |

Renewal Application - 1946 ✓
10-11-

St. Orchard
-Pr.
Ave. No. 25

Name of Owner Leonard

Labor and Mat'l. Report Sept 6 19 50

4" Main Elev. of Main at tap 4'

Gate at ● Gate at ●

● Curb Box

TAX ID# 303.18-5-11

LSM-5C 10-21-49