

### LABOR AND MATERIALS

Copper	{ Connection.....	\$	
Lead		\$	
Curb	{ Cock Valve } in.....	\$	
	{ T. S. & V. }		
Service box	{ Short 3 1/2 x 4 1/2 }		
Old returned	{ Long 4 1/2 x 5 1/2 }	\$	
	{ Buff or Rdway }		
15 Ft. 3/4 in.	{ Copper } Pipe at.....	\$	
	{ G. I. }		
	{ C.I. }		
Nipples	in. at.....	\$	
Bushings	to in. at.....	\$	
Red'g	{ Coupl'gs to in. at.....	\$	
Inc'g			
Union	in. at.....	\$	
Meter	in. at.....	\$	
Lead Joints	at.....	\$	
Compound Joints	at.....	\$	
Hrs. Water Maint. Man-1	at.....	\$	
Hrs. Water Maint. Man-2	at.....	\$	
Hrs. Labor	at.....	\$	
Hrs. Labor	at.....	\$	
Hrs. Compressor	at.....	\$	
Compensation Ins. at \$	per C.....	\$	
Trucking	.....	\$	
Pav't Patch	.....	\$	
	.....	\$	
	.....	\$	
	.....	\$	
O'head	.....	\$	
	.....	\$	

St. \_\_\_\_\_  
 Pl. 21  
 Ave. No. 21

Orville

---

Name of Owner  
Basinet

---

Measured in 1952  
Labor and Mat'l. Report July 18 1924

---

# 21

---

6" Main

Gate at ●

Elev. of Main at tap 4 1/2'

● Gate at

---

TAX ID# 309.27-1-23

---

● Curb Box