

LABOR AND MATERIALS

1 Copper	} Connection	3/4"	\$	
Lead				
1 Curb	} Cock	3/4 in.	\$	
Same				Valve
	} T.S. & V.		\$	
	} Service box	Short 3 1/2 x 4 1/2	\$	
				Long 4 1/2 x 5 1/2
				Old returned
16' 8" 3/4 in.	} Pipe at		\$	
				Copper
				G.I.
		C.I.		
1 Nipples	1/2 in. at		\$	
1 Bushings	1 to 1/2 in. at		\$	
Red'g	} Coupl'gs	to	in. at	
Inc'g				
Union	in. at		\$	
Meter	in. at		\$	
Lead Joints	at		\$	
Compound Joints	at		\$	
Maintenance Foreman			\$	
Hrs. Water Maint. Man-1	at		\$	
Hrs. Water Maint. Man-2	at		\$	
Hrs. Garage Foreman	at		\$	
Hrs. Labor	at		\$	
Hrs. Compressor	at		\$	
Compensation Ins. at \$	per C		\$	
Trucking			\$	
Pay't Patch			\$	
Tap by Miller			\$	
5-18			\$	
			\$	
O'head			\$	
			\$	

St. Orville
 -Pl.- Ave. No. 8

Name of Owner Frank Walsh

Labor and Mat'l. Report May 15 19 57

12' 6" 12' 6" 23' 8" #8

● Curb Box

6" Main Elev. of Main at tap 4-5'

Gate at ● ● Gate at

● Curb Box

TAX ID # 302.20 25-11

LSM-5C-2-5 56