

LABOR AND MATERIALS

1	Copper	} Connection <u>3/4</u>	\$	_____
	Lead			
1	Curb	} Cook Valve } 1 in.	\$	_____
			T. S. & V.	
1	Service box	} Short 3 1/2 x 4 1/2 } } Long 4 1/2 x 5 1/2 } } Buff or Rdway }	\$	_____
	● Id returned			
6'	3/4"	} Copper } } G. I. } } G. I. }	\$	_____
19	Ft. 1 in.		Pipe at	\$
	Nipples	in. at	\$	_____
	Bushings	to in. at	\$	_____
	Red'g	} Coupl'gs	\$	_____
	Inc'g		to in. at	\$
	Union	in. at	\$	_____
	Meter	in. at	\$	_____
	Lead Joints	at	\$	_____
	Compound Joints	at	\$	_____
	Maintenance Foreman		\$	_____
	Hrs. Water Maint. Man	—1 at	\$	_____
	Hrs. Water Maint. Man	—2 at	\$	_____
	Hrs. Garage Foreman	at	\$	_____
	Hrs. Labor	at	\$	_____
	Hrs. Compressor	at	\$	_____
	Compensation Ins.	at \$ _____ per C.	\$	_____
	Trucking		\$	_____
	Pav't Patch		\$	_____
	Tap Extended by		\$	_____
	Area		\$	_____
		10-11-61.	\$	_____
	O'head		\$	_____
			\$	_____

St. \_\_\_\_\_  
Pl. \_\_\_\_\_  
Ave. No. 52

Orville

Name of Owner \_\_\_\_\_

Labor and Mat'l. Report

Sept 5 or 6 1924



● Curb Box

TAX ID #

4" 309.7-11-7

Elev. of Main at tap 5'

Gate at ● old Tap. ● Gate at Near House,

● Curb Box

Tap Extended 6'  
10-11-61. 1-3/4" male Red'g  
1-3/4" curb stop.  
6-3/4" K Copper  
1-1" x 3/4" Brass Bushing  
1- curb box 3 1/2' x 4 1/2'