

LABOR AND MATERIALS

Copper	{	Connection	\$
Lead	}		
Curb	{	Cock	in. \$
		Valve	
		T. S. & V.	
Service box	{	Short 3½ X 4½	
Old returned		Long 4½ X 5½	
		Buff or Rdway	\$
Ft. in.	{	Copper	Pipe at \$
		G. I.	
		C. I.	
Nipples	in. at		\$
Bushings	to in. at		\$
Red'g	{		
Inc'g		Coupl'gs to in. at	\$
Union	in. at		\$
Meter	in. at		\$
Lead Joints	at		\$
Compound Joints	at		\$
Hrs. Water Maint. Man—1	at		\$
Hrs. Water Maint. Man—2	at		\$
Hrs. Labor—	at		\$
Hrs. Labor—	at		\$
Hrs. Compressor	at		\$
Compensation Ins. at \$	per C.		\$
Trucking			\$
Pav't Patch			\$
			\$
			\$
			\$
O'head			\$
			\$

St.
Pl. *1618*
Ave. No.

Pack Road

Name of Owner

Labor and Mat'l. Report *Mar 30* 19 *99*

RAZED 1999

● Curb Box

Main Elev. of
Main at tap

Gate at ● ● Gate at

● Curb Box

*This Place Shut off
at Main will help to
have new top*