

LABOR AND MATERIALS

1	Copper	Connection	$\frac{3}{4}$ "		\$
	Lead	Cock	$\frac{3}{4}$ in.		\$
1	Curb	Valve			\$
		T. S. & V.			\$
1	Service box	}	Short $3\frac{1}{2} \times 4\frac{1}{2}$		\$
	Old returned		Long $4\frac{1}{2} \times 5\frac{1}{2}$		\$
			Buff or Rdway		\$
19	Ft.	Copper	}	Pipe at	\$
	$\frac{3}{4}$ in.	G.I.			\$
		C.I.			\$
	Nipples	in.		at	\$
	Bushings	to		in. at	\$
	Red'g	}	Coupl'gs	to	\$
	Inc'g				in. at
	Union	in.		at	\$
	Meter	in.		at	\$
	Lead Joints			at	\$
	Compound Joints			at	\$
	Maintenance Foreman				\$
	Hrs. Water Maint. Man-1			at	\$
	Hrs. Water Maint. Man-2			at	\$
	Hrs. Garage Foreman			at	\$
	Hrs. Labor			at	\$
	Hrs. Compressor			at	\$
	Compensation Ins. at \$			per C	\$
	Trucking				\$
	Pav't Patch:				\$
	Tap by Giscardt				\$
	Co. 3-18-59				\$
	(Leak)				\$
	O'head				\$
					\$

St. _____
 Pt. 32-42
 Ave. No. _____

Park

Name of Owner _____

Labor and Mat'l. Report Mar. 18 1959

#42

Gulf Sta.

45'2"

55'2"

● Curb Box

6" Main
Elev. of Main at tap 7

Gate at ●
● Gate at

Shutoff At Curb 2/6/55

● Curb Box
 This Tap Feeds #42
 Star Service Center
~~#55 Hoag's Office~~
(P. S. S. S.)

LSM-SC-2-B 56