

### LABOR AND MATERIALS

1	<del>Copper</del> <del>Lead</del>	Connection	2" x 6"		\$
1	Curb	Cock Valve T. S. & V.	2 in.	at main	\$
	Service box Old returned		Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff or Rdway		\$
16	Ft. 2 in.	Copper C. I. C. I.		Pipe at	\$
	Nipples	in. at			\$
	Bushings	to in. at			\$
	Red'g Inc'g	Coupl'gs	to in. at		\$
	Union	in. at			\$
	Meter	in. at			\$
	Lead Joints	at			\$
	Compound Joints	at			\$
	Maintenance Foreman				\$
	Hrs. Water Maint. Man	1 at			\$
	Hrs. Water Maint. Man	2 at			\$
	Hrs. Garage Foreman	at			\$
	Hrs. Labor	at			\$
	Hrs. Compressor	at			\$
	Compensation Ins.	at \$	per C		\$
	Trucking				\$
	Pav't Patch				\$
					\$
					\$
					\$
	O'head				\$
					\$

St. 53  
Pl. 53  
Ave. No. 53

Name of Owner Wesley  
Campbell Wholesale

Labor and Mat'l. Report (May 1) 1915



● Curb Box

Main	Elev. of Main at tap
Gate at ●	● Gate at

● Curb Box