

LABOR AND MATERIALS

1 Copper Lead } Connection  $3/4$ " \$  
 1 Curb } Cock Valve }  $3/4$ " Oriseal. \$  
 } T.S. & V. }  
 1 Service box { Short  $3\frac{1}{2}$  x  $4\frac{1}{2}$  }  
 Old returned { Long  $4\frac{1}{2}$  x  $5\frac{1}{2}$  } \$  
 } Buff or Rdway }  
 11 Ft.  $3/4$  in. { Copper } Pipe at \$  
 } G.I. }  
 } G.I. }  
 Nipples in. at \$  
 Bushings to in. at \$  
 Red'g }  
 Inc'g } Coupl'gs to in. at \$  
 Union in. at \$  
 Meter in. at \$  
 Lead Joints at \$  
 Compound Joints at \$  
 Maintenance Foreman \$  
 Hrs. Water Maint. Man-1 at \$  
 Hrs. Water Maint. Man-2 at \$  
 Hrs. Garage Foreman at \$  
 Hrs. Labor at \$  
 Hrs. Compressor at \$  
 Compensation Ins. at \$ per C \$  
 Trucking \$  
 Pav't Patch \$  
 Tap by Lareau & Co. \$  
 6-2-67. \$  
 O'head \$

Park St. ? 66  
 Ave. No. 68

Name of Owner Aganelli.

Labor and Mat'l. Report June 2 1967.

6" Main Elev. of Main at tap 4'

Gate at • Gate at

• Curb Box

• Curb Box

LSM-BC-3-10-61