

Labor and Materials

Lead Connection	\$
Curb Cock	\$
Service Box (Short 3 1/2 x 4 1/2)	\$
Old returned (Long 4 1/2 x 5 1/2)	\$
Buffalo	\$
Ft. in. G. I. Pipe at	\$
Nipples in. at	\$
Bushings to in. at	\$
Red'g Coup to in. at	\$
Inc'g Coup to in. at	\$
Union in. at	\$
Meter in. at	\$
Cu. Yds. Br. Stone at	\$
Cu. Yds. Sand at	\$
Bags Cement at	\$
Paving Brick (Mack Red Asphalt) at	\$
Hrs. Foreman at	\$
Hrs. Common Labor at	\$
Hrs. Mason at	\$
Hrs. at	\$
Hrs. at	\$
Builders' Use of Water	\$
..... at	\$
..... at	\$
..... at	\$
..... at	\$
Total	\$ 11.84	

and Material Report

19 11

114
Park St. 114



Main

Elev. of Main at tap

Gate at ●

● Gate at

● Curb Box

Shut off at Curb

7-14-1925