

LABOR AND MATERIALS

Copper } Connection	\$
Lead } Connection	\$
Curb { Clock Valve in.	\$
{ T. S. & V. }	\$
Service box } Short 3/4X4/4	\$
Old returned } Long 4/4X5/4	
} Buff or Rdway	
Ft. in. } Copper	\$
} Galv. Iron	
} Cast Iron	
Nipples in. at	\$
Bushings to in. at	\$
Red'g } Couplings to in. at	\$
Inc'g }	
Union in. at	\$
Meter in. at	\$
Lead Joints at	\$
Compound Joints at	\$
Hrs. Foreman at	\$
Hrs. Gnauffour at	\$
Hrs. Tapper at	\$
Hrs. Labor at	\$
Hrs. Labor at	\$
Hrs. Compressor at	\$
Compensation Ins.	\$
Trucking	\$
Builders Use of Water	\$
	\$
	\$
	\$
	\$
	\$

St. ✓
Pl.
Ave. No.

Park St

Name of Owner 100-106 Glen St
Post Star Building

labor and Mat'l. Report April 29 1948

# 12714	16-18
------------	-------

100-106
2nd Valve ● Curb Box
Park St

Main Elev. of
Main at tap

Gate at ● ● Gate at
See 100-106 Glen St.
Card for Post Star Tap

Shut off at curb ● Curb Box

This shut off Post Star
Post Star also 16-18 + Road
Kahig-Salvation Army
Auto repair Shop

LSM-5C-6-1-45