

LABOR AND MATERIALS

1	Copper Lead	} Connection	3/4		\$
1	Curb	{ Cock Valve T. S. & V. }	3/4	in.	\$
	Same Service Box Old returned	{ Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff for Rdway }			\$
23	Ft.	3/4 in.	{ Copper Galv Iron Cast Iron }	Pipe at	\$
	Nipples	in.	at		\$
	Bushings	to	in.	at	\$
1	Red'g Ino'g	} Couplings	3/4	to	in.
	Union	in.	at		\$
	Meter	in.	at		\$
	Lead Joints	at			\$
	Leadite Joints	at			\$
2	Hrs.	Foreman	at		\$
	Hrs.	Chauffeur	at		\$
	Hrs.	Tapper	at		\$
15	Hrs.	Labor	at		\$
	Hrs.	Labor	at		\$
	Hrs.	Compressor	at		\$
	Compensation	Ins.			\$
	Trucking				\$ 1.00
110	Builders Use of Water				\$
					\$
					\$
					\$
					\$
					\$
					\$
					\$

St. 9
 Pt. _____
 Ave. No. 3

Pearl

Name of Owner Doty

Labor and Mat'l. Report Sept 2 1925

9

16'9" 3'13" Curb Box

8" 1968
4 Main

Elev. of Main at tap 5'

Gate at ● ● Gate at

● Curb Box

TAX ID # 303.17-10-23