

Labor and Materials

..	Copper	Connection.....	\$1.50
..	Curb	{ Cock Valve } ..in.	\$1.70
..	Service Box	{ Short 3/4x4 1/2 } ..	\$1.54
..	Old returned	{ Long, 4 1/2 x 5 1/2 } ..	
..	24 Ft. 3/4 in.	{ Copper Galv. Iron } Pipe at ..	\$4.56
..	Nipples	..in. at ..	\$
..	Bushingsto ..in. at ..	\$
..	Red'g Inc'g	{ Couplings.....to ..in. at ..	\$
..	Union.....	in. at ..	\$
..	Meter.....	in. at ..	\$
..	Lbs. Br. Stone	at ..	\$
..	Lbs. Sand	at ..	\$
..	Bags Cement	at ..	\$
..	Paving Brick	{ Mack Red Asphalt } at ..	\$
..	Lead Joints	at ..	\$
..	Leadite Joints	at ..	\$
6	Hrs. Foreman	at ..	\$3.75
15	Hrs. Common Labor	at ..	\$6.75
..	Hrs. Common Labor	at ..	\$
..	Hrs. Mason	at ..	\$
..	Hrs. Masons Helper	at ..	\$
2	Hrs. Compressor	at ..	\$3.-
..	Compensation Ins	\$0.38
..	Trucking	\$1.-
..	Builders Use of Water	Paul Patch ..	\$9.-
Total			\$33.18

53 34 27-29
 Labor and Material Report *Aug 7* 19*10*

21 Pearl *Franklin*

27-29

Curb Box

12" Main *Lawrence St.* Rev. of Main at tap *5*

Gate at *27 TAX ID # 303.17-10-13* Gate at

Curb Box

old Tap shut off at main

TO SHUT OFF TURN!
COUNTER CLOCKWISE
Reverse

MD