

Labor and Materials

.....Copper } Connection.....	\$.....
.....Lead }	\$.....
.....Curb { Cock Valve T.S.&V. }	\$.....
.....Service Box { Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 }	\$.....
.....Old returned { Buff. or Rdway }	\$.....
.....Ft.in. { Copper Galv. Iron Cast Iron } Pipe at	\$.....
.....Nipplesin. at	\$.....
.....Bushingstoin. at.....	\$.....
.....Red'g } Couplings.....to.....in.at.....	\$.....
.....Inc'g }	\$.....
.....Union.....in. at	\$.....
.....Meter.....in. at	\$.....
.....Lbs. Br. Stone at	\$.....
.....Lbs. Sand at	\$.....
.....Bags Cement at	\$.....
.....Paving Brick { Mack Red Asphalt } at	\$.....
.....Lead Joints at	\$.....
.....Leadite Joints at	\$.....
.....Hrs. Foreman at	\$.....
.....Hrs. Common Labor at	\$.....
.....Hrs. Common Labor at	\$.....
.....Hrs. Mason at	\$.....
.....Hrs. Masons Helper at	\$.....
.....Hrs. Compressor at	\$.....
.....Compensation Ins	\$.....
.....Trucking	\$.....
.....Builders Use of Water	\$.....
Total \$.....	

Labor and Material Report

Dec 31 1935

44 Rock Ave



Main

Elev of Main at tap

Gate at

TAX ID #

303.18-10-7

Gate at

● Curb Box

Measured Dec 31-35

By J. P. ...

J. J. ...