

LABOR AND MATERIALS

Copper	} Connection	_____	\$	_____			
Lead							
Curb	} Cock	} _____ in.	\$	_____			
					} Valve		
						T. S. & V.	
Service box	} Short 3 1/2 x 4 1/2	} _____	\$	_____			
Old returned					Long 4 1/2 x 5 1/2		
8 Ft. 1 1/2 in.	} Copper	} Pipe at	\$	_____			
Nipples	in. at	_____	\$	_____			
Bushings	to _____ in. at	_____	\$	_____			
Red'g	} Coupl'gs.	to _____ in. at	\$	_____			
Inc'g							
Union	in. at	_____	\$	_____			
Meter	in. at	_____	\$	_____			
_____			\$	_____			
Compound Joints	at	_____	\$	_____			
Maintenance Foreman		_____	\$	_____			
Hrs. Water Maint. Man-1	at	_____	\$	_____			
Hrs. Water Maint. Man-2	at	_____	\$	_____			
Hrs. Garage Foreman	at	_____	\$	_____			
Hrs. Labor-	at	_____	\$	_____			
Hrs. Compressor	at	_____	\$	_____			
_____			\$	_____			
Trucking		_____	\$	_____			
Pav't Patch		_____	\$	_____			
_____			\$	_____			
_____			\$	_____			
_____			\$	_____			
_____			\$	_____			

St. _____
No. 14

PINE

Name of Owner

GARAGE

Labor and Mat'l. Report

MAY 14 19 56

22'4" 44'5"

● Curb Box

6" Main Elev. of Main at tap 5'

Gate at ● ● Gate at

● Curb Box