

Labor and Materials

.....Copper } Connection.....	3	\$ 96
.....Lead }	3	\$ 1.33
.....Curb { Cock Valve T.S.&V. }	3	\$ 1.35
.....Service Box { Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 }		\$ 1.35
.....Old returned { Buff. or Rawl. }		
2 1/2 Ft.in. { Copper Galv. Iron Cast Iron } Pipe at	15	\$ 39.0
.....Nipplesin. at		\$
.....Bushingstoin. at		\$
.....Red'g Inc'g } Couplings.....to.....in.at		\$
.....Union.....in. at		\$
.....Meter.....in. at		\$
.....Lbs. Br. Stone at		\$
.....Lbs. Sand at		\$
.....Bags Cement at		\$
.....Paving Brick { Mack Red Asphalt } at		\$
.....Lead Joints at		\$
.....Leadite Joints at		\$
.....Hrs. Foreman at		\$
.....Hrs. Common Labor at		\$
.....Hrs. Common Labor at		\$
.....Hrs. Mason at		\$
.....Hrs. Masons Helper at		\$
.....Hrs. Compressor at		\$
.....Compensation Ins		\$
.....Trucking		\$
.....Builders Use of Water (Sewer)		\$ 2.50
Total \$.....		

5-36
Labor and Material Report

July 9 1936

21 Pine St



39' 7"

49' 6"

Curb Box

6 Main

Elev. of Main at tap 5 1/2

Gate at TAX ID# 309.27-4-3 Gate at

Curb Box

old shut off
New House

[Handwritten signature]