

LABOR AND MATERIALS

1	Copper	} Connection	3/4"	\$	_____
1	Lead		} Gock Valve F.S. & V.	3/4 in.	\$
1	Curb				
1	Service box	} Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff or Rdway		\$	_____
13	Old returned				
13	Ft. 3/4 in.	} Copper G.I. G.I.	Pipe at	\$	_____
	Nipples	in. at		\$	_____
	Bushings	to in. at		\$	_____
	Red'g Inc'g	} Coupl'gs.	to in. at	\$	_____
	Union		in. at		\$
	Meter	in. at		\$	_____
	Lead Joints	at		\$	_____
	Compound Joints	at		\$	_____
	Maintenance Foreman			\$	_____
	Hrs. Water Maint. Man-1	at		\$	_____
	Hrs. Water Maint. Man-2	at		\$	_____
	Hrs. Garage Foreman	at		\$	_____
	Hrs. Labor	at		\$	_____
	Hrs. Compressor	at		\$	_____
	Compensation Ins.	at \$ _____ per C.		\$	_____
	Trucking			\$	_____
	Pav't Patch			\$	_____
	Tap by Gifford & Co				
	4-26-60.				
	O'head			\$	_____
				\$	_____

St. _____
Pl. _____
Ave. No. 27

Name of Owner
Pine
Susan David.

Labor and Mat'l. Report April 26 1960

18' 10" 10' 4"

● Curb Box

8" Main Elev. of Main at tap 5'

Gate at ● ● Gate at

● Curb Box

Crandall St.

PINE ST

LSM-5C-2-5-55