LABOR AND MATERIALS

1	Copper ~~Lead~~ Connection 3/4	$ 1.35
1	Curb {Cock ~~Valve~~ T. S. & V.} 3/4 in.	$ 1.80
	Service Box Old returned {Short 3⅛x4⅛ Long 4⅛x5⅛ Buff or Rdway}	$ —
9	Ft. 3/4 in. {Copper Galv Iron Cast Iron} Pipe at 18	$ 1.62
	Nipples in. at	$
	Bushings to in. at	$
	Red'g Inc'g {Couplings to in. at	$
	Union in. at	$
	Meter in. at	$
	Lead Joints at	$
	Leadite Joints at	$
	Hrs. Foreman at	$
1	Hrs. Chauffeur at 62½	$ .62
3/4	Hrs. Tapper at "	$ 1.88
4	Hrs. Labor at 45	$ 1.80
	Hrs. Labor at	$
3/4	Hrs. Compressor at 62½	$ .46
	Compensation Ins.	$ .14
	Trucking	$ 1.—
	Builders Use of Water Before Pouring	$ —
	Tapping Hassel	$
/	/	$
		$
		$
		$ 10.67

4 1941

Platt St. ~~Pl.~~ Ave. No. 2

Name of Owner

Hot Taps

Labor and Mat'l. Report Aug 14 1941

4 Main

Elev. of Main at tap 7

Gate at ●

● Gate at

● Curb Box

measured from
#3 Platt St.
7