

Labor and Materials

Copper } Connection.....	3	\$ 1.25
Lead }	3	
Curb { Cock }	3	\$ 1.70
{ Valve }		
{ Flange }		
Service Box { Short 3 3/4 x 4 1/2 }		\$ 1.45
Old returned { Long 4 1/2 x 5 1/2 }		
{ Bolt, or Nut }		
27 Ft. 3/4 in. { Copper } Pipe at 12 1/2		\$ 3.45
{ Galv. Iron }		
{ Cast Iron }		
Nipples		\$
Bushings		\$
Red'g } Couplings.....to.....in.at.....		\$
Inc'g }		
Union.....in. at		\$
Meter.....in. at		\$
Lbs. Br. Stone at		\$
Lbs. Sand at		\$
Bags Cement at		\$
Paving Brick { Mack } at		\$
{ Red }		
{ Asphalt }		
Lead Joints at		\$
Leadite Joints at		\$
7 Hrs. Foreman at	6 7/8	\$ 4.38
17 Hrs. Common Labor at	50	\$ 4.00
8 Hrs. Common Labor at	45	\$ 3.60
Hrs. Mason at		\$
Hrs. Masons Helper at		\$
Hrs. Compressor at		\$
Compensation Ins		\$ 45
Trucking		\$ 1.00
Builders Use of Water	1.00	\$ 1.00
Total		\$ 21.18

335-8 15 19 33

Labor and Material Report

11 Platt St

36' 10"

15'

36'-8"

Curb Box

Main Elev. of Main at tap 5 1/2

Gate at 10' 303.18-13.8 Gate at

TAX

Curb Box

old dug up & shut off at main
to be charged to owner

11/8