LABOR AND MATERIALS

1 Copper ~~Lead~~	Connection 3/4	$ 1.23
1 Curb { Cock ~~Valve~~ ~~T. S. & V.~~ }	3/4 in.	$ 1.68
1 Service Box Old returned { Short 3½x4½ Long 4½x5½ Buff. or Rdway }		$ 1.54
~~26~~ Ft. 3/4 in. { Copper ~~Galv. Iron~~ ~~Cast Iron~~ }	Pipe at 17	$ 4.76
____ Nipples ____ in. at		$
____ Bushings ____ to ____ in. at		$
____ Red'g Inc'g { Couplings ____ to ____ in. at		$
____ Union ____ in. at		$
____ Meter ____ in. at		$
____ Lead Joints at		$
____ Leadite Joints at		$
____ Hrs. Foreman at		$
4 Hrs. Chauffeur at 62½		$ 2.50
4 Hrs. Tapper at ~~5~~		$ 2.50
12 Hrs. Labor at 45		$ 5.40
____ Hrs. Labor at		$
____ Hrs. Compressor at		$
____ Compensation Ins.		$ .32
____ Trucking		$ 1.—
____ Builders Use of Water Patch		$ .5—
Tap by Person		$
		$
old Tap to be dug up		$
		$
		$ 25.93

41 - 1939

St. 19-21

Pl.

Platt

Aver No. 15

Name of Owner

Foley

Labor and Mat'l. Report July 7 1939

4 Main

Elev. of Main at tap 5/

Gate at ●

● Gate at

#21 TAX ID # 303.18-13-6

● Curb Box

old Shut off