

### Labor and Materials

1	Copper } Connection		\$ 3 20
	Head		
1	Curb { Cock Valve P. S. & V. }	in.	\$ 10 00
1	Service Box { Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 } Old returned		\$ 13 00
8	Ft. in. { Copper Galv. Iron } Pipe at		\$ 17 60
	Nipples	in. at	\$
7	Bushings 3/4 to 1/2 in.	at	\$ 08
	Red'g } Couplings	to in. at	\$
	Inc'g }		
	Union	in. at	\$
	Meter	in. at	\$
	Lbs. Br. Stone	at	\$
	Lbs. Sand	at	\$
	Bags Cement	at	\$
	Paving Brick { Mack Red Asphalt }	at	\$
	Lead Joints	at	\$
	Leadite Joints	at	\$
5	Hrs. Foreman at	62.5	\$ 31 25
15	Hrs. Common Labor at	50	\$ 75 00
	Hrs. Common Labor	at	\$
	Hrs. Mason	at	\$
	Hrs. Mason's Helper	at	\$
	Hrs. Compressor	at	\$
	Compensation Ins.		\$ 28
	Trucking		\$ 1 00
	Builders' Use of Water		\$
Total			\$ 192 40

### Labor and Material Report

19

26-102 42

34. 0. 1. 2. 3. 4. 5. 6. 7. 8. 9. 10. 11. 12. 13. 14. 15. 16. 17. 18. 19. 20. 21. 22. 23. 24. 25. 26. 27. 28. 29. 30. 31. 32. 33. 34. 35. 36. 37. 38. 39. 40. 41. 42.

PORT 42



6 Main Elev. of Main at tap 5  
 Gate at ● Gate at ●

● Curb Box

TAX ID# 303.18-6-6