

Labor and Materials

Copper	Lead	Connection ^{3/4}	\$	
1	Curb	Cock Valve	\$	
		T.S.&V.	\$	
1	Service Box	Short 3 1/2 x 4 1/2	\$	
		Old returned Long 4 1/2 x 5 1/2	\$	
12	Ft.	in.		
		Copper Pipe at	\$	
		Galv. Iron	\$	
		Cast Iron	\$	
	Nipples	in. at	\$	
	Bushings	to in. at	\$	
	Red'g Inc'g	Couplings	to in. at	\$
	Union	in. at	\$	
	Meter	in. at	\$	
	Lbs. Br. Stone	at	\$	
	Lbs. Sand	at	\$	
	Bags Cement	at	\$	
	Paving Brick	Mack Red Asphalt	at	\$
	Lead Joints	at	\$	
	Leadite Joints	at	\$	
	Hrs. Foreman	at	\$	
	Hrs. Common Labor	at	\$	
	Hrs. Common Labor	at	\$	
	Hrs. Mason	at	\$	
	Hrs. Masons Helper	at	\$	
	Hrs. Compressor	at	\$	
	Compensation Ins		\$	
	Trucking		\$	
	Builders Use of Water		\$	
Total \$				

87

Labor and Material Report

Sept 11

1935

3/4 tap at 65 Platt St.



6" Main

Elev. of Main at tap 5'

Gate at ●

● Gate at

● Curb Box

TAX ID # 303.14-3-28