

### Labor and Materials

1	Copper } Connection		\$ 3.20
1	Curb } Cock Valve } T.S. & V. } 3/4 in.		\$ 1.00
1	Service Box } Short 3 1/2 x 4 1/2 } Old returned } Long 4 1/2 x 5 1/2 } Buff. or Rdway }		\$ 1.30
5 1/2	Pt. } 3/4 in. } Copper Galy. Iron } Cast Iron } Pipe at		\$ 3.08
	Nipples	in. at	\$
	Bushings	to in. at	\$
1	Redg } Couplings } In. } to in. at		\$ 1.5
	Union	in. at	\$
	Meter	in. at	\$
	Lbs. Br. Stone at		\$
	Lbs. Sand at		\$
	Bags Cement at		\$
	Paving Brick } Mack } Red } Asphalt } at		\$
	Lead Joints at		\$
	Leadite Joints at		\$
	Hrs. Foreman at		\$
2	Hrs. Common Labor at	67.5	\$ 1.25
2	Hrs. Common Labor at	50	\$ 1.00
	Hrs. Mason at		\$
	Hrs. Mason's Helper at		\$
	Hrs. Compressor at		\$
	Compensation Ins.		\$ .27
	Trucking		\$ 1.00
	Builders' Use of Water		\$
Total			\$ 12.05

26-143

Labor and Material Report

1926

67 Plaza St



4" Main

Elev. of Main at tap

Gate at ●

● Gate at

● Curb Box

TAX ID # 303.14-3-14