

### LABOR AND MATERIALS

1	Copper Lead	} Connection	3/4		\$ 2.80
1	Curb	Clock Valve I. S. & V.	3/4	in.	\$ 3.60
1	Service box Old returned	} Short 3 1/2 X 4 1/2 Long 4 1/2 X 6 1/2 Buff or Rdway			} Same \$ —
15	Ft. 3/4 in.				
	Nipples	in. at			\$
	Bushings	to	in. at		\$
	Red'g Inc'g	} Couplings	to	in. at	\$
	Union		in. at		
	Meter	in. at			\$
	Lead Joints at				\$
	Compound Joints at				\$
	Hrs. Foreman at				\$
7	Hrs. Chauffeur at	91			\$ 6.37
1	Hrs. Tapper at				\$
15	Hrs. Labor at	80			\$ 12.00
	Hrs. Labor at				\$
	Hrs. Compressor at				\$
	Compensation Ins.				\$ 41
	Trucking				\$ 1.50
	Builders Use of Water				\$ 10.90
	Tap by <i>W. H. Sinsler</i>				\$
					\$
					\$
					\$
					\$ 42.33

109  
 St. Platt  
 Pl. 87  
 Ave. No. 87

---

Name of Owner  
Hurley

---

Labor and Mat'l. Report Aug 26 1947

---

4 Main Elev. of Main at tap 4

Gate at ● ● Gate at

---

● Curb Box