

LABOR AND MATERIALS

Copper	}	Connection		\$	
Lead					
Curb	}	Cock	in.	\$	
		Valve			
		T. S. & V.			
Service box	}	Short 3½ x 4½	}	\$	
Old returned		Long 4½ x 5½			
		Buff or Rdway			
Ft. in.	}	Copper	} Pipe at	\$	
		G. I.			
		C. I.			
Nipples	in. at			\$	
Bushings	to in. at			\$	
Red'g	}	Coupl'gs	to in. at	\$	
Inc'g					
Union	in. at			\$	
Meter	in. at			\$	
Lead Joints	at			\$	
Compound Joints	at			\$	
Maintenance Foreman				\$	
Hrs. Water Maint. Man-1	at			\$	
Hrs. Water Maint. Man-2	at			\$	
Hrs. Garage Foreman	at			\$	
Hrs. Labor	at			\$	
Hrs. Compressor	at			\$	
Compensation Ins.	at \$	per C		\$	
Trucking				\$	
Pay't Patch				\$	
				\$	
				\$	
O'head				\$	
				\$	

St. _____
Pt. _____
Ave. No. 118

UPPER-PLATT

Name of Owner KEN WHITING?

CORENTO

RE MEASURED

Labor and Mat'l. Report Aug. 12 19 81

UPPER
PLATT

● Curb Box

Elev. of Main at tap _____

Gate at ● _____ ● Gate at _____

● Curb Box

TEL
POLE
35'
21' Main

P. LEP #26

TAX ID # 303.14-1-6.
OR 303.10-2-3

LSM-5C-6-1-67