

Labor and Materials

Copper } Connection.....	3	\$ 2.60
Lead }	1/2	
Curb } Cock Valve }	1	\$ 2.30
} T.S. & V. }	1	
Service Box } Short 3/4x4 1/2 }		\$ 1.40
Old returned } Long 1 1/2x5 1/2 }		
} Buff. or Rdway }		
6 Ft. } in. } Copper } Galv. Iron } Pipe at.....	3	\$ 1.59
}		
} Cast Iron }		
Nipples.....	in. at.....	\$
Bushings.....	to..... in. at.....	\$
Red'g } Couplings.....	to..... in. at.....	\$
Inc'g }		
Union.....	in. at.....	\$
Meter.....	in. at.....	\$
Lbs. Br. Stone at.....		\$
Lbs. Sand at.....		\$
Bags Cement 'at.....		\$
Paving Brick } Mack } at.....		\$
} Red }		
} Asphalt }		
Lead Joints at.....		\$
Leadite Joints at.....		\$
2 Hrs. Foreman at.....		\$ 1.25
4 Hrs. Common Labor at.....		\$ 1.63
Hrs. Common Labor at.....		\$
Hrs. Mason at.....		\$
Hrs. Mason's Helper at.....		\$
Hrs. Compressor at.....		\$
Compensation Ins.....		\$.00
Trucking.....		\$ 1.00
Builders' Use of Water.....	Patch	\$ 5.00
Total		\$ 16.75

29-117 13
Labor and Material Report

19 27



4 Main

Elev of Main at tap

Gate at ●

● Gate at

● Curb Box

Old top down's indicated

*3/4" COPPER
 6' TO MAIN*