

Labor and Materials

.. Copper } Connection.....	3	\$	1.25
.. Lead }			
.. Curb { Cock Valve T.S.&V. } 3/4 in.....	3	\$	1.70
.. Service Box { Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff. or Rawer }		\$	1.27
7 Ft. 3/4 in. { Copper Galv. Iron Cast Iron } Pipe at 13 1/2		\$	95
.. Nipples		\$	
.. Bushings		\$	
.. Red'g Inc'g } Couplings.....		\$	
.. Union.....		\$	
.. Meter.....		\$	
.. Lbs. Br. Stone at		\$	
.. Lbs. Sand at		\$	
.. Bags Cement at		\$	
.. Paving Brick { Mack Red Asphalt } at		\$	
.. Lead Joints at		\$	
.. Leadite Joints at		\$	
3 Hrs. Foreman at	62 hr	\$	1.88
8 Hrs. Common Labor at	45	\$	3.60
.. Hrs. Common Labor at		\$	
.. Hrs. Mason at		\$	
.. Hrs. Masons Helper at		\$	
.. Hrs. Compressor at		\$	
.. Compensation Ins		\$.21
.. Trucking		\$	1.-
.. Builders Use of Water Patch		\$	5.-
Total			\$16.96

1935-103 86 30 1935

Labor and Material Report *Aug*

68 Prospect St

6 Main Elev. of Main at tap 3 1/2

Gate at TAX ID # 303.13-20-7 Gate at

● Curb Box

old shut off at main
3/4" copper
7' to main