

LABOR AND MATERIALS

Copper	Connection	3/4		\$ 2.94
Lead				
Curb	Cock	3/4	in.	\$ 3.71
	Valve			
	T. S. & V.			
Service box	Short	3 1/2 X 4 1/2		\$ 5.90
	Long	4 1/2 X 5 1/2		
Old returned	Buff or Rdway			
33 Ft. 3/4 in.	Copper	Pipe at	30	\$ 9.90
	G. I.			
	C. I.			
Nipples	in. at			\$
Bushings	to in. at			\$
Red'g				
Inc'g	Coupl'gs. to in. at			\$
Union	in. at			\$
Meter	in. at			\$
Lead Joints	at			\$
Compound Joints	at			\$
2 Hrs. Water Maint. Man-1	at	1.01		\$ 2.02
20 Hrs. Water Maint. Man-2	at	91		\$ 18.20
15 Hrs. Labor	at	80		\$ 12.00
Hrs. Labor	at			\$
4 Hrs. Compressor	at	1.20		\$ 4.80
Compensation Ins.	at \$ per C.			\$ 71
Trucking				\$ 1.00
Pav't Patch				\$ 3.30
T. S. & V. McGowan				\$
O'head				\$
				\$ 74.48

67

St.

Pl.

Ave. No. 91

Prospect

Name of Owner

Del Signore

Labor and Mat'l. Report

June 15 1948



● Curb Box

6 Main

Elev. of

Main at tap

Gate at ●

● Gate at

TAX ID # 303.13-21-17

● Curb Box

3/4" copper
33' to MAIN