

LABOR AND MATERIALS

Copper	Lead	Connection		\$
Curb	}	Cock Valve	in.	\$
		T. S. & V.		
Service box	}	Short 3 1/2 x 4 1/2		
Old returned		Long 4 1/2 x 5 1/2		
		Buff or Rdway		\$
Ft. 3/4 in.	}	Copper	Pipe at	\$
		G. I.		
		C. I.		
Nipples	in.	at		\$
Bushings	to	in.	at	\$
Red'g	}	Coupl'gs	to in. at	\$
Inc'g				
Union	in.	at		\$
Meter	in.	at		\$
Lead Joints	at			\$
Compound Joints	at			\$
Maintenance Foreman				\$
Hrs. Water Maint. Man-1	at			\$
Hrs. Water Maint. Man-2	at			\$
Hrs. Garage Foreman	at			\$
Hrs. Labor	at			\$
Hrs. Compressor	at			\$
Compensation Ins. at \$		per C		\$
Trucking				\$
Pav't Patch				\$
				\$
				\$
O'head				\$
				\$

SE.
PT.
Ave. No. _____

Prugn's Island

Name of Owner _____

Labor and Mat'l. Report *June 1986*

3/4" service in vicinity of canal bridge

● Curb Box

	Elev. of
Main	Main at tap _____
Gate at ●	● Gate at

● Curb Box

3/4" COPPER