

LABOR AND MATERIALS

Copper } Connection \_\_\_\_\_ \$  
 Lead }  
 Curb } Cock } \_\_\_\_\_ in. \$  
       } Valve }  
       } T. S. & V. }  
 Service box } Short 3½ x 4½ }  
 Old returned } Long 4½ x 5½ } \_\_\_\_\_ \$  
 16½<sup>1</sup> Ft. 3/4 in. } Copper } Pipe at \_\_\_\_\_ \$  
                   } G.I. }  
                   } C.I. }  
 Nipples \_\_\_\_\_ in. at \_\_\_\_\_ \$  
 Bushings \_\_\_\_\_ to \_\_\_\_\_ in. at \_\_\_\_\_ \$  
 Red'g }  
 Inc'g } Coupl'gs. \_\_\_\_\_ to \_\_\_\_\_ in. at \_\_\_\_\_ \$  
 Union \_\_\_\_\_ in. at \_\_\_\_\_ \$  
 Meter \_\_\_\_\_ in. at \_\_\_\_\_ \$  
 \_\_\_\_\_ \$  
 Compound Joints at \_\_\_\_\_ \$  
 Maintenance Foreman \_\_\_\_\_ \$  
 Hrs. Water Maint. Man-1 at \_\_\_\_\_ \$  
 Hrs. Water Maint. Man-2 at \_\_\_\_\_ \$  
 Hrs. Garage Foreman \_\_\_\_\_ at \_\_\_\_\_ \$  
 Hrs. Labor \_\_\_\_\_ at \_\_\_\_\_ \$  
 Hrs. Compressor at \_\_\_\_\_ \$  
 \_\_\_\_\_ \$  
 Trucking \_\_\_\_\_ \$  
 Pav't Patch \_\_\_\_\_ \$  
 \_\_\_\_\_ \$  
 \_\_\_\_\_ \$  
 \_\_\_\_\_ \$  
 \_\_\_\_\_ \$

PRUYN'S ISLAND

KAMYR

St.

Pl. No.

Ave. No.

Name of Owner

FINCH PRUYN - LOG CUTTING

Labor and Mat'l. Report

12-14 1999

3/4" Copper  
 16 1/2' to MAIN

● Curb Box

Main \_\_\_\_\_ Elev. of Main at tap \_\_\_\_\_  
 Gate at ● \_\_\_\_\_ Gate at ● \_\_\_\_\_

