

LABOR AND MATERIALS

1 Copper } Connection 2" \$  
~~Lead~~ }  
 1 Curb } Cock Valve } 2 in. \$  
           } T.S. & V. }  
 1 Service box { Short 3 1/2 x 4 1/2 }  
 Old returned { Long 4 1/2 x 5 1/2 } Orisecal 6'  
                   { Buff or Rdway } \$  
 10 Ft. 2" in. { Copper } Pipe at \$  
                   { G.I. }  
                   { C.I. }  
 Nipples in. at \$  
 Bushings to in. at \$  
 Red'g }  
 Inc'g } Coupl'gs to in. at \$  
 Union in. at \$  
 Meter in. at \$  
 Lead Joints at \$  
 Compound Joints at \$  
 Maintenance Foreman \$  
 Hrs. Water Maint. Man-1 at \$  
 Hrs. Water Maint. Man-2 at \$  
 Hrs. Garage Foreman at \$  
 Hrs. Labor at \$  
 Hrs. Compressor at \$  
 Compensation Ins. at \$ per C \$  
 Trucking \$  
 Pav't Patch \$  
 Tap by Howe + Co \$  
           11-6-78 \$  
 O'head \$  
 \$

Pruyn's Island

Murray St Ext. St. Pl. Ave. No.

Name of Owner

Alstrom Trading

Labor and Mat'l. Report Jan 6 1978

21'-6" Curb Box

8" Main

Elev. of Main at tap 6-7'

Gate at •

• Gate at

• Curb Box

2" COPPER  
 10' TO MAIN