

**Labor and Materials**

1	Copper	} Connection	.....	\$ 2.60
1	Lead			
1	Curb	} Cock Valve T.S.&V.	..... in	\$ 2.77
1	Service Box		} Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2	.....
1	Old returned	} Buff. or Raway		.....
10	Ft. 3/4 in.		} Copper Galv. Iron Cast Iron	Pipe at
	Nipples			..... in. at
	Bushings		..... to ..... in. at	\$
	Red'g Inc'g	} Couplings	..... to ..... in. at	\$
	Union			..... in. at
	Meter		..... in. at	\$
	Lbs. Br. Stone		at	\$
	Lbs. Sand		at	\$
	Bags Cement		at	\$
	Paving Brick	} Mack Red Asphalt	at	\$
	Lead Joints			at
	Leadite Joints		at	\$
1	Hrs. Foreman		at	\$ 45
1	Hrs. Common Labor		at	\$ 45
	Hrs. Common Labor		at	\$
	Hrs. Mason		at	\$
	Hrs. Masons Helper		at	\$
	Hrs. Compressor		at	\$
	Compensation Ins			\$ .04
	Trucking			\$ 1-
	Builders Use of Water			\$
Total \$				10.77

32-15 40 Gnade St.  
 Labor and Material Report *April 18* 1932  
 J. Hoag & Gardner  
 # 40  
 45 ft  
 37 ft  
 8 ft  
 Brick way  
 Curb Box  
 6 Main Elev. of Main at tap 4 1/2  
 Gate at TAX ID# 302.19-14-3 Gate at  
 Curb Box  
 # 2  
 3/4" COPPER  
 10' to MAIN