

Labor and Materials

Copper	} Connection		
Lead			
1/2 Curb	} Cock Valve T.S.&V.	3/4 in	\$ 1.70
1 Service Box		} Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff. or Rdway	
Old returned			
25 Ft. 3/4 in.	} Copper Galv. Iron Cast Iron	Pipe at 13 1/2 cts.	\$ 3.28
Nipples			
Bushings			
1 Red's Inc's	} Couplings Iron to Brass		\$.60
Union			
Meter			
Lbs. Br. Stone			
Lbs. Sand			
Bags Cement			
Paving Brick	} Mack Red Asphalt	at	
Lead Joints			
Leadite Joints			
Hrs. Foreman		62 hr.	
14 Hrs. Common Labor		45	\$ 6.30
Hrs. Common Labor			
Hrs. Mason			
Hrs. Masons Helper			
Hrs. Compressor			
Compensation Ins			\$.24
Trucking			\$ 1.-
Builders Use of Water		Patch	\$ 2.50
Total			\$ 17.09

1935-111

Labor and Material Report *Oct. 12* 19*35*

Quade Ave 3/4 tap
Quade

Main Elev of Main at tap

Gate at ● ● Gate at

● Curb Box

Now Tap
3/4" copper
25' to main

JM