

Labor and Materials

Copper	} Connection..... ?	\$ 2.70	
Lead			
Curb	} Cock Valve } T-S & V. } .. in. ?	\$ 2.39	
Service Box	} Short 3/4x1/2 } } Long 4 1/2x5/8 } } Buff or Rdway }	\$ 1.45	
Old returned			
6 Ft.	} Copper } } Galv. Iron } Pipe at .. ?	\$ 2.16	
			} Cast Iron }
Nipples	.. in. at ..	\$.	
Bushings	.. to .. in. at ..	\$.	
Red'g	} Couplings .. to .. in. at ..	\$.	
Inc'g			
Union	.. in. at ..	\$.	
Meter	.. in. at ..	\$.	
Lbs. Br. Stone	at ..	\$.	
Lbs. Sand	at ..	\$.	
Bags Cement	at ..	\$.	
Paving Brick	} Mack } } Red } at ..	\$.	
			} Asphalt }
Lead Joints	at ..	\$.	
Leadite Joints	at ..	\$.	
2 Hrs. Foreman	at ..	\$ 1.25	
1 1/2 Hrs. Common Labor	at ..	\$ 5.40	
Hrs. Common Labor	at ..	\$.	
Hrs. Mason	at ..	\$.	
Hrs. Mason's Helper	at ..	\$.	
Hrs. Compressor	at ..	\$.	
Compensation Ins.	at ..	\$ 7.1	
Trucking	at ..	\$ 1. =	
Builders' Use of Water	Patch	\$ 5. =	
Total \$		71.56	

⑪ Labor and Material Report

October 21/30

Raymond Ave.

No Measurement

● Curb Box

4" Main

Elev of Main at tap 4 1/2'

Gate at ●

TAX ID # 303.9-10-8

● Gate at

● Curb Box

This house

3/4" copper
6' to MAIN