ar w		
Ridge	St. Pl. No. 237	
Name of Owner		
Fred Hu	rne .	
Labor and Mat'l. Report 177aq 20 1964.		
26 >	37'	
(Curb Box	
6" Mein	Elev. of 5-1/2	
Gate at ●	• Gate at	
• Curb Box		
3/4" - 14'	COPPER	
:LSM—8C—3-10-61	e*	

237 RIDG	Ave. No
14% 10 "	303.9-12-8
Labor and Mat'l, Report	19
Labor and Wat I, Report	19
_	
	/ .
211	35'
26'	
	Curb Box
	CLEAPOUT
	Elev. of
Main	Main at tap
Sate at	• Gate a
	• Gate a

RECEIVED

JAN 15 2018

City of Glens Falls W.W.T.P.

LABOR AND MATERIALS	
Copper Connection 34.	\$
Cock Valve T. S. & V. Short 3½ x 4½	\$
Old returned Long 4½ x 5½ Buff or Rdway	\$
Ft. Copper G. I. Pipe at Pripe at	\$
Nipplesin. at	\$
Bushings to in. at	\$
Red'g Coupl'gs to in. at	s
Unionin, at	
Meterin.at	Highlight Court of the Court of
Lead Joints at	
Compound Joints at	
Maintenance Foreman	
Hrs. Water Maint, Man—1 at	
Hrs. Water Maint. Man—2 at	
Hrs. Garage Foreman at	
Hrs. Labor— at	S
Hrs. Compressor at	
Compensation Ins. at \$per C	
Trucking	
Pay't Patch	9
TOD BY (91 5 401 d to	Ф -e
1000	9
5-20-64.	\$S
O'head	S
	S
	φ
a a constant of the constant o	

LABOR AND MATERIALS

Copper Connection	\$
Curb \ \frac{\text{Cock}}{\text{Valve}} \ \text{T.S. & V.} \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	
Service box Short 3-1/2 x 4-1/2 Old returned Long 4-1/2 x 5-1/2	\$
—— Ft in. $\left\{egin{array}{l} ext{Copper} \\ ext{G.I.} \\ ext{C.I.} \end{array} ight\}$ Pipe at	\$
Nipples in, at	\$
Bushings to in. at	
Red'g	
Inc'g	
Union in. at	\$
Meter in. at	\$
Compound Joints at	_ \$
Maintenance Foreman	
Hrs. Water Maint, Man - 1 at	
Hrs. Water Maint. Man - 2 at	
Hrs. Garage Foreman at	_ \$
Hrs. Labor at	_ \$
Hrs. Compressor at	\$
	\$
Trucking	\$
Pav't Patch	
	\$
	\$
	\$
	\$
	9