

75-46 ✓

St. Ridge Ave. No. 187 239

Name of Owner Bakst

Labor and Mat'l. Report Sept 27 1946

6 Main Elev. of Main at tap 5

Gate at ● Gate at ●

● Curb Box

Tap on Sanford St.  
3/4" - 22' copper

LSM-5C-6-1-45

239 RIDGE<sup>+</sup> SP  
Pl. Ave. No. \_\_\_\_\_

Name of Owner TAX ID # 303.9-12-7

Labor and Mat'l. Report 19 \_\_\_\_\_

Gate at ● Gate at ●

● Curb Box

**RECEIVED**  
**JAN 15 2018**  
 City of Glens Falls  
 W.W.T.P.

### LABOR AND MATERIALS

1	Copper Lead	Connection	3/4	\$	1.79
1	Curb	Clock Valve T.S. & V.	3/4 in.	\$	2.61
1	Service box Old returned	Short 3" X 4" Long 4" X 5" Buffer Rdway		\$	1.42
22	Ft. 3/4 in.	Copper Galv. Iron Cast Iron	Pipe at	\$	
	Nipples	in. at		\$	
	Bushings	to in. at		\$	
	Red'g Inc'g	Couplings	to in. at	\$	
	Union	in. at		\$	
	Meter	in. at		\$	
	Lead Joints at			\$	
	Compound Joints at			\$	
	Hrs. Foreman at			\$	
8	Hrs. Chauffeur at	8 1/2		\$	6.60
	Hrs. Tapper at			\$	
2	Hrs. Labor at	7 1/2		\$	1.43
	Hrs. Labor at			\$	
	Hrs. Compressor at			\$	
	Compensation Ins.			\$	.22
	Trucking			\$	1.-
	Builders Use of Water			\$	5.-
	Tap by Warsawski			\$	
	Pipe furnished by			\$	
	Water			\$	

This tap on Sanford 20.47

### LABOR AND MATERIALS

	Copper Lead	Connection		\$	
	Curb	Cock Valve T.S. & V.	in.	\$	
	Service box Old returned	Short 3-1/2 x 4-1/2 Long 4-1/2 x 5-1/2		\$	
	Ft. in.	Copper G.I. C.I.	Pipe at	\$	
	Nipples	in. at		\$	
	Bushings	to in. at		\$	
	Red'g			\$	
	Inc'g			\$	
	Union	in. at		\$	
	Meter	in. at		\$	
				\$	
	Compound Joints at			\$	
	Maintenance Foreman			\$	
	Hrs. Water Maint. Man - 1 at			\$	
	Hrs. Water Maint. Man - 2 at			\$	
	Hrs. Garage Foreman	at		\$	
	Hrs. Labor	at		\$	
	Hrs. Compressor at			\$	
				\$	
	Trucking			\$	
	Pav't Patch			\$	
				\$	
				\$	
				\$	
				\$	