

LABOR AND MATERIALS

1	Copper	{ Connection	3/4	\$	2.27
	Lead				
1	Curb	{ Cock Valve F.S. & V.	3/4 in.	\$	2.70
1	Service box	{ Short 3 1/2 x 4 1/2			
	Old returned	{ Long 4 1/2 x 5 1/2		\$	4.25
		{ Buff or Rdway			
30	Ft.	{ Copper	Pipe at 35	\$	10.50
		{ G.I.			
		{ C.I.			
	Nipples	in. at		\$	
	Bushings	to in. at		\$	
	Red'g	{ Coupl'gs to in. at		\$	
	Inc'g				
	Union	in. at		\$	
	Meter	in. at		\$	
	Lead Joints	at		\$	
	Compound Joints	at		\$	
	Hrs. Water Maint. Man-1	at		\$	
9	Hrs. Water Maint. Man-2	at 1.02		\$	9.18
	Hrs. Labor	at		\$	
21	Hrs. Labor	at 91		\$	19.11
3	Hrs. Compressor	at 1.20		\$	3.60
	Compensation Ins. at \$2.226 per C.			\$	6.3
	Trucking			\$	1.00
	Pav't Patch			\$	18.48
	Tap by Moquin			\$	
	O'head			\$	
				\$	71.72

53.24

St. Ridge
 Pl-
 Ave. No. 106

Name of Owner Gubitz

Labor and Mat'l. Report Oct. 6 1950

#106

30' 3" 28' 0"

● Curb Box

10 Main Elev. of Main at tap 5'

Gate at ● ● Gate at

● Curb Box

3/4" copper
30' to main