Labor and Materials

1	Copper / ~~Lead~~ — Connection	3/4	$ 1.41
1	Curb — Cock / ~~Valve~~ / ~~T. S. & V.~~	3/4 in	$ 1.93
1	Service Box Old returned — ~~Short 3½ x 4½~~ / Long 4½ x 5½ / ~~Buff. or Rdway~~		$ 1.77
13	Ft. 3/4 in. — Copper / ~~Galv. Iron~~ / ~~Cast Iron~~ — Pipe at		$ 2.86
	Nipples	in. at	$
	Bushings	to in. at	$
	Red'g Inc'g — Couplings	to in. at	$
	Union	in. at	$
	Meter	in. at	$
	Lead Joints at		$
	Leadite Joints at		$
	Hrs. Foreman at		$
3	Hrs. Chauffeur at		$ 1.98
1	Hrs. Tapper at		$ .67
1½	Hrs. Labor at		$ 2.03
	Hrs. Labor at		$
	Hrs. Compressor at		$
	Compensation Ins.		$ .17
	Trucking		$ 1.—
	Builders Use of Water		$
			$
			$
			$
	Tap by Hand		$
			$ 14.62

1 4 3 - 1937

116-120

St.
Pl.
Ave. Ridge St No. 82

Name of Owner

Butler

Labor and Mat'l. Report Sept 3 1937

116-120

This tap on Washington St

6 Main

Elev. of Main at tap 5

Gate at Shutoff at Curb 7-17-73

Curb Box

194'

Curb Box for 120 Ridge St

Curb Box for 24 E. Washington