

Oct. 29 19

Labor and Material Report

Ridge St.
Henechay

139 Ridge?

● Curb Box

Main Elev. of Main at tap

Gate at ● Gate at

● Curb Box

Tovment

31-160. 139 H.B.C.D. 19

Labor and Material Report

99-97 1/2 - 101-100 Ridge St

139 28'-0" 45'-0"

● Curb Box

8" Main Elev. of Main at tap

Gate at ● Gate at

TAX 10# 303.17-8-9

● Curb Box

Old tap shut off

Remeasured June 25-75

3/4" copper

14' to main

Labor and Materials

Lead Connection ²	\$
Curb Cock	\$
Service Box (Short 8 1/2 x 4 1/2)	\$
Old returned (Long 4 1/2 x 5 1/2)	\$
Buffalo	\$
11 Ft. in. G. I. Pipe at	\$
Nipples in. at	\$
Bushings to in. at	\$
Red'g Coup. to in. at	\$
Inc'g Coup. to in. at	\$
Union in. at	\$
Meter in. at	\$
Cu. Yds. Br. Stone at	\$
Cu. Yds. Sand at	\$
Bags Cement at	\$
Paving Brick { Mack Red Asphalt } at	\$
4 Hrs. Foreman at	\$
2 Hrs. Common Labor at	\$
Hrs. Mason at	\$
Hrs. at	\$
Hrs. at	\$
Builders' Use of Water	\$
at	\$ 1.00
at	\$
at	\$
at	\$
Total	\$ 13.79

Labor and Materials

1 Copper } Connection ^{3/4}	\$ 2.60
Lead	
1 Curb { Cock Valve F.S. & V. } ^{3/4} in.	\$ 2.27
1 Service Box { Short 3 1/2 x 1 1/2 Long 4 1/2 x 5 1/2 Buff. or Rdway }	\$ 1.59
Old returned	
14 Ft. ^{3/4} in. { Copper Galv. Iron Cast Iron } Pipe at	\$ 2.57
Nipples in. at	\$
Bushings to in. at	\$
Red'g } Couplings to in. at	\$
Inc'g }	
Union in. at	\$
Meter in. at	\$
Lbs. Br. Stone at	\$
Lbs. Sand at	\$
Bags Cement at	\$
Paving Brick { Mack Red Asphalt } at	\$
Lead Joints at	\$
Leadite Joints at	\$
5 1/2 Hrs. Foreman at	\$ 3.14
2 1/2 Hrs. Common Labor at	\$ 1.25
12 1/2 Hrs. Common Labor at	\$ 5.63
Hrs. Mason at	\$
Hrs. Mason's Helper at	\$
1 Hrs. Compressor at	\$ 1.50
Compensation Ins	\$.32
Trucking	\$ 1.-
Builders' Use of Water Patch	\$ 23.-

Total \$ 45.12