

LABOR AND MATERIALS

Copper } Connection		\$
Lead } <i>gate valve,</i>		
1 CurbT } <i>in.</i>		\$
	<i>Turn in many</i>	
	<i>times for</i>	
Service box } Short 3 1/2 x 4 1/2		\$
Old returned } Long 4 1/2 x 5 1/2		
	<i>on 4055,</i>	
	Buff or Rdway	\$
Ft. in. } Copper	Pipe at	\$
	G. I.	
	C. I.	
Nipples	in. at	\$
Bushings	to in. at	\$
Red'g } Coupl'gs	to in. at	\$
Inc'g }		
Union	in. at	\$
Meter	in. at	\$
Lead Joints	at	\$
Compound Joints	at	\$
Maintenance Foreman		\$
Hrs. Water Maint. Man-1	at	\$
Hrs. Water Maint. Man-2	at	\$
Hrs. Garage Foreman	at	\$
Hrs. Labor	at	\$
Hrs. Compressor	at	\$
Compensation Ins. at \$	per C	\$
Trucking		\$
Pav't Patch		\$
		\$
		\$
		\$
O'head		\$
		\$

St. Ridge
 Pl. 192
 Ave. No. 192

Name of Owner _____

Remeasured Nov. 15-67

Labor and Mat'l. Report ? 19 ?

Ridge St.

62' 4" 60' 10"

● Curb Box

William St.

4" Main Elev. of Main at tap 5'

Gate at ● ● Gate at

● Curb Box

Tap on William St.

LSM-5C-6-1-67

Labor and Materials

.....Copper	} Connection.....
.....Lead			
.....Curb	{ Cock Valve T.S.&V. }in\$
.....Service Box			
.....Old returned	{ Short 3½x4½ Long 4½x5½ Buff. or Rdway }\$
.....Ft.....fn.			
.....Nipples	{ Copper Galv. Iron Cast Iron }	Pipe at\$
.....Bushingstoin. at\$
.....Red'g Inc'g	} Couplings.....toin.at
.....Union.....			
.....Meter.....in.	at\$
.....Lbs. Br. Stone	at\$
.....Lbs. Sand	at\$
.....Bags Cement	at\$
.....Paving Brick	{ Mack Red Asphalt }	at\$
.....Lead Joints			
.....Leadite Joints	at\$
.....Hrs. Foreman	at\$
.....Hrs. Common Labor	at\$
.....Hrs. Common Labor	at\$
.....Hrs. Mason	at\$
.....Hrs. Masons Helper	at\$
.....Hrs. Compressor	at\$
.....Compensation Ins\$
.....Trucking\$
.....Builders Use of Water\$
Total \$.....		

195

Labor and Material Report 19

Curb Box at 149 Ridge St

Main	Elev of Main at tap
------	------------------------

Gate at ● ● Gate at

● Curb Box

#195 - Ridge + William

TAX 10# 303.13-8-21