

**Labor and Materials**

1	Copper Lead	Connection	3/4"	\$	2.60
1	Curb	Cock Valve T.S. & V.	2" in.	\$	2.27
1	Service Box Old returned	Short 3/4x1 1/2 Long 1 1/2x3 1/2 Bull on Redway		\$	1.59
13	Ft.	3/4" in.	Copper Galv. Iron Cast Iron Pipe at	\$	2.34
	Nipples	in. at		\$	
	Bushings	to in. at		\$	
	Red'g Inc'g	Couplings	to in. at	\$	
	Union	in. at		\$	
	Meter	in. at		\$	
	Lbs. Br. Stone	at		\$	
	Lbs. Sand	at		\$	
	Bags Cement	at		\$	
	Paving Brick	Mack Red Asphalt	at	\$	
	Lead Joints	at		\$	
	Leadite Joints	at		\$	
5 1/2	Hrs. Foreman			\$	3.44
2 1/2	Hrs. Common Labor at	Tapper		\$	1.25
12 1/2	Hrs. Common Labor at			\$	5.63
	Hrs. Mason at			\$	
	Hrs. Mason's Helper at			\$	
1	Hrs. Compressor at			\$	1.50
	Compensation Ins			\$	32
	Trucking			\$	1.-
	Builders' Use of Water	Patch		\$	23.-

Total \$ 44.94

31-173 207

Labor and Material Report

1931

3/4" tap at 159' ridge at



6" Main Elev of Main at tap 412.11

Gate at TAX ID # 303.13-8-17 Gate at

● Curb Box

Old tap shut off

3/4" - 13' copper