

Labor and Materials

| | | |
|--|----------|---------|
| Copper } Connection..... | 3 | 1.33 |
| Lead } | 4 | |
| Curb { Cock Valve T.S.&V. } | in | 1.58 |
| Service Box { Short 3 1/2 x 4 1/2 } | | 1.36 |
| Old returned { Long 4 1/2 x 5 1/2 } | | |
| 12 Ft. 3/4 in. { Copper Galv. Iron Cast Iron } Pipe at | | 1.14 |
| Nipples | in. at | |
| Bushings | to | in. at |
| Red'g Inc'g } Couplings | to | in. at |
| Union | in. at | |
| Meter | in. at | |
| Lbs. Br. Stone at | | |
| Lbs. Sand at | | |
| Bags Cement at | | |
| Paving Brick { Mack Red Asphalt } at | | |
| Lead Joints at | | |
| Leadite Joints at | | |
| 3 Hrs. Foreman at | | 1.88 |
| 8 Hrs. Common Labor at | 4 | |
| Hrs. Common Labor at | | |
| Hrs. Mason at | | |
| Hrs. Masons Helper at | | |
| Hrs. Compressor at | | |
| Compensation Ins | | 1.18 |
| Trucking | | 1.18 |
| Builders Use of Water Patch | | 5.00 |
| Total | | \$17.47 |

33-76 209 Oct 10 1933

Labor and Material Report

161 Ridge St Hunter St

4 Main Elev of Main at tap 4 1/2

Gate at TAX 107 303.13-1-28 Gate at

● Curb Box

old tap shut off

3/4" - 12' COPPER

D.W.